EEPROM XTRA. KIT APPLICATIONS

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
ABARTH						
500	-	2007	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Grande Punto	-	2005	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
ACURA						
CL	1996	2004	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Integra	1997	2004	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
MDX	2000	2007	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
NSX	1997	2006	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
RL	2002	2007	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
RSX	2002	2007	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
TL	1999	2004	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
ALFA ROMEO						
145	1995	2001	93c46 8pin, 128 Bytes	AR1505TK1	-	Philips® fixed code PH00 (33)
146	1995	2001	93c46 8pin, 128 Bytes	AR1505TK1	-	Philips® fixed code PH00 (33)
155	1995	1998	93c46 8pin, 128 Bytes	AR1505TK1	-	Philips® fixed code PH00 (33)
164	1995	1998	93c46 8pin, 128 Bytes	AR16U/AR16TK1	TK100	Philips® fixed code PH00 (33)
GTV	1995	1998	93c46 8pin, 128 Bytes	AR1505TK1	-	Philips® fixed code PH00 (33)
Mito	-	2008	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Spider	1995	1998	93c46 8pin, 128 Bytes	AR1505TK1	-	Philips® fixed code PH00 (33)
AUDI						
80	1996	-	93c46 8pin, 128 Bytes	V35U	TK100	Megamos® fixed code MG00 (13)
A4	1996	1998	93c46 8pin, 128 Bytes	V66U/V66TK/V66-KF	TK100/GKM	Megamos® fixed code MG00 (13)
A6	1995	1997	93c46 8pin, 128 Bytes	V35U/V66U/V66TK/V66-KF	TK100/GKM	Megamos® fixed code MG00 (13)
BUICK						
Regal	-	2012	Atmel 16K	-	-	Philips® Crypto PH20 (46)
CHEVROLET						
Aveo	-	2012	Atmel 16K	-	-	Philips® Crypto PH20 (46)
Aveo	2006	2008	93c56 8pin, 256 Bytes	DAE48SU	TKM	Megamos® Crypto MG10 (48)
Camaro	2010	2014	24c16 8pin, 2048 Bytes	VX5U/VX5BTK/VX5-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Camaro	-	2015	24C32	-	-	Philips® Crypto PH20 (46)
Captiva	2006	2010	95040, 8pin, 512 Bytes	DAE47U/DAE47TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Cobalt	2006	2010	95040, 8pin, 512 Bytes	B106U/B106TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Cruze	-	2007	24c16 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
HHR	2006	2010	95040, 8pin, 512 Bytes	B106U/B106TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Kalos	2006	2008	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Matiz	-	2005	93c56 8pin, 256 Bytes	DAE49U	TKM	Megamos® Crypto MG10 (48)
Onyx	-	2012	Atmel 16K	-	-	Philips® Crypto PH20 (46)
CHRYSLER						
Ypsilon	1996	2003	Motorola MC68HC05E6, 28pin, 160 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
CHRYSLER						
Ypsilon	1996	2003	Motorola MC68HC08AZ32, 64pin, 512 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)
CITROËN						
Berlingo	1998	2001	93c46 8pin, 128 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Berlingo	-	2008	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Evasion	1998	2002	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Evasion	1998	2002	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Evasion	1998	2002	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Jumper	1996	2001	93c46 8pin, 128 Bytes	FT50U/FT50TK/FT50ATK5	TK100/GKM	Megamos® fixed code MG00 (13)
Jumper	2006	2011	95320 8pin, 4096 Bytes	-	-	Megamos® Crypto MG10 (48)
Jumper	2006	2011	95160, 8pin, 2048 Bytes	-	-	Megamos® Crypto MG10 (48)
Jumpy/Dispatch	1998	2001	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Jumpy/Dispatch	1998	2001	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Jumpy/Dispatch	1998	2001	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Jumpy/Dispatch	1998	2001	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Nemo	-	2008	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Relay	1996	2001	93c46 8pin, 128 Bytes	FT50U/FT50TK/FT50ATK5	TK100/GKM	Megamos® fixed code MG00 (13)
Relay	2006	2011	95320 8pin, 4096 Bytes	-	-	Megamos® Crypto MG10 (48)
Relay	2006	2011	95160, 8pin, 2048 Bytes	-	-	Megamos® Crypto MG10 (48)
Relay	2010	2015	95160, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Saxo	1996	2003	93c46 8pin, 128 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Synergie	1998	2002	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Synergie	1998	2002	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Synergie	1998	2002	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Xantia	1997	1999	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Xantia	1998	1999	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Xsara	1998	2001	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Xsara	1998	2001	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
DAEWOO						
Aranos	-	1997	Motorola MC68HC05B6 52pin, 256 Bytes	-	-	Megamos® fixed code MG00 (13)
Cielo	-	1997	Motorola MC68HC05B6 52pin, 256 Bytes	-	-	Megamos® fixed code MG00 (13)
Espero	-	1997	Motorola MC68HC05B6 52pin, 256 Bytes	DAE46TK1/DAE46STK1	GKM	Megamos® fixed code MG00 (13)
Lacetti	2002	2005	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Lanos	1997	2002	Motorola MC68HC05B6 52pin, 256 Bytes	DAE47SU/DAE47STK1	TK100/GKM	Megamos® fixed code MG00 (13)
Leganza	1997	2000	Motorola MC68HC05B6 52pin, 256 Bytes	DAE47U/DAE47TK1	TK100/GKM	Megamos® fixed code MG00 (13)
Leganza	2001	2002	93c56 8pin, 256 Bytes	DAE47SU/DAE47STK1	TKM/GKM	Megamos® Crypto MG10 (48)
Matiz	1998	2000	Motorola MC68HC05B6 52pin, 256 Bytes	DAE47SP	-	Megamos® fixed code MG00 (13)
Nexia	1995	1997	Motorola MC68HC05B6 52pin, 256 Bytes	DAE46TK1	GKM	Megamos® fixed code MG00 (13)
Nubira	1997	2000	Motorola MC68HC05B6 52pin, 256 Bytes	DAE48SU/DAE48STK1	TK100/GKM	Megamos® fixed code MG00 (13)
Nubira	2000	2002	93c56 8pin, 256 Bytes	DAE48U/DAE48TK1	TKM/GKM	Megamos® Crypto MG10 (48)
Tacuma	2000	2006	93c56 8pin, 256 Bytes	DAE48SU/DAE48STK1	TKM/GKM	Megamos® Crypto MG10 (48)
Windstorm	2006	2010	95040, 8pin, 512 Bytes	-	-	Philips® Crypto PH20 (46)
DAIHATSU						
Cuore	1998	2006	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Move	1997	2002	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Sirion	1998	2004	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
DAIHATSU						
Terios	1997	2005	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Various	1998	1999	93c66 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Various	1998	2000	93c66 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
DUCATI						
600	-	1997	24c02 8pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
600	-	1997	24c16 8pin, 2048 Bytes	-	-	Temic® fixed code TM10 (11)
620	-	2006	24c02 8pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
620	-	2006	24c16 8pin, 2048 Bytes	-	-	Temic® fixed code TM10 (11)
749	2003	2006	24c02 8pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
749	2003	2006	24c16 8pin, 2048 Bytes	-	-	Temic® fixed code TM10 (11)
800	2003	2006	24c02 8pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
800	2003	2006	24c16 8pin, 2048 Bytes	-	-	Temic® fixed code TM10 (11)
900	1999	-	24c02 8pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
900	1999	-	24c16 8pin, 2048 Bytes	-	-	Temic® fixed code TM10 (11)
999	2003	2006	24c02 8pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
999	2003	2006	24c16 8pin, 2048 Bytes	-	-	Temic® fixed code TM10 (11)
1000	-	2006	24c02 8pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
1000	-	2006	24c16 8pin, 2048 Bytes	-	-	Temic® fixed code TM10 (11)
FIAT						
500	-	2007	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Barchetta	1995	2002	93c46 8pin, 128 Bytes	FT1505TK5	GKM	Megamos® fixed code MG00 (13)
Brava	1995	1997	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Bravo	1995	1997	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Bravo	1997	2001	Motorola MC68HC05E6, 28pin, 160 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic® fixed code TM10 (11)
Bravo	1997	2001	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic® fixed code TM10 (11)
Bravo	-	2007	95320 8pin, 4096 Bytes	-	-	Megamos® Crypto MG10 (48)
Bravo	-	2007	95160, 8pin, 2048 Bytes	-	-	Megamos® Crypto MG10 (48)
Bravo	2009	2011	95160, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Cinquecento	1995	1998	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Coupe	1995	2000	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/TK5	Philips® fixed code PH00 (33)
Croma	1995	1997	93c46 8pin, 128 Bytes	FT50U/FT50TK	TK100/TK5	Philips® fixed code PH00 (33)
Doblò	-	2006	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Doblò	2000	2007	93c66 8pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Ducato	1996	2001	93c46 8pin, 128 Bytes	FT50U/FT50TK	TK100/GKM	Megamos® fixed code MG00 (13)
Ducato	2006	2011	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Ducato	2006	2011	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Ducato	2010	2010	95160, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Fiorino	-	2007	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Grande Punto	-	2005	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Idea	2003	2009	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Linea	-	2007	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Linea	-	2007	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Marea	1996	2002	Motorola MC68HC05E6, 28pin, 160 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic® fixed code TM10 (11)
Marea	1996	2002	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic® fixed code TM10 (11)
Marengo	1996	2001	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Multipla	1998	2010	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT1505U/FT1505CTK	TKM/GKM	Megamos® Crypto MG10 (48)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
FIAT						
Palio	1996	2001	Motorola MC68HC05E6, 28pin, 160 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic® fixed code TM10 (11)
Palio	1996	2001	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic® fixed code TM10 (11)
Panda	1995	2002	93c46 8pin, 128 Bytes	FT50U/FT50TK	TK100/GKM	Megamos® fixed code MG00 (13)
Panda	2002	2009	Motorola MC68HC912DG128 112pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Panda	2002	2009	Motorola MC9S12DG128 112pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Panda	2002	2009	MC9S12DP256 112pin, 4096 Bytes	-	-	Philips® Crypto PH20 (46)
Punto	1995	1999	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Punto	2001	2007	93c66 8pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Punto	-	2005	95320 8pin, 4096 Bytes	FT50U/FT50TK	TKM/GKM	Megamos® Crypto MG10 (48)
Punto	-	2005	95160, 8pin, 2048 Bytes	FT50U/FT50TK	TKM/GKM	Megamos® Crypto MG10 (48)
Scudo	1996	2001	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Scudo	1996	2001	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Scudo	1997	1999	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Seicento	1997	2000	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Siena	2001	2007	93c66 8pin, 512 Bytes	FT50U/FT50TK	TKM/GKM	Megamos® Crypto MG10 (48)
Stilo	-	2007	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Stilo	-	2007	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Strada	2001	2007	93c66 8pin, 512 Bytes	-	-	Megamos® Crypto MG10 (48)
Tempra	1995	1996	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Ulysse	1996	2002	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Ulysse	1996	2002	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Ulysse	1996	2002	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
FORD						
Courier	1998	2002	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Escort	1995	2000	TMS370C702, 28pin, 256 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Expedition	1997	2003	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Explorer	1997	1999	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Fiesta	2002	2010	93c56 8pin, 256 Bytes	-	-	Texas® Crypto TPXX (4D)
Fiesta	2002	2010	93c86(28000766), 8pin, 2048 Bytes	-	-	Texas® Crypto TPXX (4D)
Focus	2004	2010	93c86(28000766), 8pin, 2048 Bytes	FD40U/FD40BTK/FD40-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Ka	1997	2002	TMS370C702, 28pin, 256 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Mondeo	1995	2000	TMS370C702, 28pin, 256 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Mustang	1996	2004	TMS370C702, 28pin, 256 Bytes	FD21U/FD21BTK/FD21-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Puma	1998	2001	TMS370C702, 28pin, 256 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Ranger	-	2007	93c86(28000766), 8pin, 2048 Bytes	-	-	Texas® Crypto TPXX (4D)
Scorpio	1995	1998	TMS370C702, 28pin, 256 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Taurus	-	2000	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Transit	1995	2000	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Windstar	1999	2000	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
HOLDEN						
Commodore	2013	2017	95320 8pin, 4096 Bytes	-	-	Philips® Crypto PH20 (46)
HONDA						
Accord	1995	1999	Motorola MC68HC05B6 52pin, 256 Bytes	RV3U/RV3TK1	TK100	Philips® fixed code PH00 (33)
Civic	1995	2001	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Civic	1995	2001	Motorola MC68HC05B6 52pin, 256 Bytes	HD90U/HD90TK	TK100/TK5	Philips® fixed code PH00 (33)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
HONDA						
Civic	2006	2011	24c04 8pin, 512 Bytes	HD1U/HD1BTK/HD1-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
CR-V	1997	1999	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Integra	1998	2001	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Legend	1996	2004	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Odyssey	-	2005	24c02 8pin, 256 Bytes	HD1U/HD1BTK/HD1-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Passport	1998	2002	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Prelude	1997	2002	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Shuttle	1995	2000	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
HYUNDAI						
Accent	1996	1999	93c56 8pin, 256 Bytes	HY10U/HY10TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Accent	-	2004	95160, 8pin, 2048 Bytes	HY10U/HY10TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Atos	1997	2000	93c56 8pin, 256 Bytes	HY10U/HY10TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Galloper	1999	2003	93c56 8pin, 256 Bytes	HY10U/HY10TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
H200	-	-	93c56 8pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
i10	-	2010	95160, 8pin, 2048 Bytes	HY14U/HY14TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
i30	-	2010	95160, 8pin, 2048 Bytes	TR49U/TR49TK/TR49-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Santa Fe	2000	2005	93c56 8pin, 256 Bytes	-	-	Texas® Crypto TPXX (4D)
ISUZU						
Dmax	-	2010	93c66 8pin, 512 Bytes	TR47SU/TR47STK/TR47-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
IVECO						
Daily	1998	2001	93c46 8pin, 128 Bytes	FT50U/FT50TK	TK100/TK5	Philips® fixed code PH00 (33)
Daily	2006	2011	95320 8pin, 4096 Bytes	-	-	Megamos® Crypto MG10 (48)
Daily	2006	2011	95160, 8pin, 2048 Bytes	-	-	Megamos® Crypto MG10 (48)
Daily	2012	2015	95640	-	-	Philips® Crypto PH20 (46)
Eurocargo	-	2007	95320 8pin, 4096 Bytes	-	-	Megamos® Crypto MG10 (48)
Eurocargo	-	2007	95160, 8pin, 2048 Bytes	-	-	Megamos® Crypto MG10 (48)
JAGUAR						
XJ6	1994	1997	93c46 8pin, 128 Bytes	-	-	Megamos® fixed code MG00 (13)
XJS	1994	1997	93c46 8pin, 128 Bytes	-	-	Megamos® fixed code MG00 (13)
XK	1994	1997	93c46 8pin, 128 Bytes	-	-	Megamos® fixed code MG00 (13)
XK8	1994	1997	93c46 8pin, 128 Bytes	-	-	Megamos® fixed code MG00 (13)
JEEP						
Patriot	-	2007	24c16 8pin, 2048 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Wrangler	-	2007	24c16 8pin, 2048 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
KIA						
Rio	2001	2005	93c46 8pin, 128 Bytes	KI3SU/KI3STK	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Sportage	2001	2003	93c46 8pin, 128 Bytes	KI3SU/KI3STK	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
LANCIA						
Dedra	1995	1997	93c46 8pin, 128 Bytes	LA1505TK5	GKM	Megamos® fixed code MG00 (13)
Dedra	1997	1999	93c46 8pin, 128 Bytes	LA1505TK5	GKM	Megamos® fixed code MG00 (13)
Dedra	1997	1999	Motorola MC68HC05E6, 28pin, 160 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
LANCIA						
Dedra	1997	1999	Motorola MC68HC08AZ32, 64pin, 512 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)
Delta	1995	1999	93c46 8pin, 128 Bytes	LA1505TK5	-	Megamos® fixed code MG00 (13)
Delta	2010	2011	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
K	1995	2001	93c46 8pin, 128 Bytes	AR20U	TK100	Philips® fixed code PH00 (33)
K Coupe	1997	2001	93c46 8pin, 128 Bytes	AR20U	TK100	Philips® fixed code PH00 (33)
Lybra	1999	2006	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Musa	2010	2011	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Ypsilon	1996	2003	Motorola MC68HC05E6, 28pin, 160 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)
Ypsilon	1996	2003	Motorola MC68HC08AZ32, 64pin, 512 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)
Ypsilon	-	2007	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Ypsilon	-	2007	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Zeta	1996	2002	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Zeta	1996	2002	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Zeta	1996	2002	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
MAZDA						
2	2002	2010	93c56 8pin, 256 Bytes	-	-	Texas® Crypto TPXX (4D)
2	2002	2010	93c86(28000766), 8pin, 2048 Bytes	-	-	Texas® Crypto TPXX (4D)
MERCEDES						
Actros	1998	2006	93c56 8pin, 256 Bytes	YS15TK1	GKM	Megamos® fixed code MG00 (13)
Actros	1998	2006	93c66 8pin, 512 Bytes	YS15TK1	GKM	Megamos® fixed code MG00 (13)
Actros	1998	2006	93c86(28000766), 8pin, 2048 Bytes	YS15TK1	GKM	Megamos® fixed code MG00 (13)
Atego	1998	2006	93c56 8pin, 256 Bytes	-	-	Megamos® fixed code MG00 (13)
Atego	1998	2006	93c66 8pin, 512 Bytes	-	-	Megamos® fixed code MG00 (13)
Atego	1998	2006	93c86(28000766), 8pin, 2048 Bytes	-	-	Megamos® fixed code MG00 (13)
Axor	1998	2006	93c56 8pin, 256 Bytes	-	-	Megamos® fixed code MG00 (13)
Axor	1998	2006	93c66 8pin, 512 Bytes	-	-	Megamos® fixed code MG00 (13)
Axor	1998	2006	93c86(28000766), 8pin, 2048 Bytes	-	-	Megamos® fixed code MG00 (13)
MITSUBISHI						
3000 GT	1996	2001	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Carisma	1996	2000	93c46 8pin, 128 Bytes	VL15TK1	-	Philips® fixed code PH00 (33)
Chariot	1996	2000	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Colt	1996	2000	24c01, 8pin, 128 Bytes	MT8SU/MT8SBTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Eclipse	1996	2000	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Expo	1996	2000	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Express	1996	2000	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Galant	1996	2000	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Grandis	-	2006	24c02 8pin, 256 Bytes	-	-	Philips® Crypto PH20 (46)
L200	-	2006	24c02 8pin, 256 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
L200	-	2009	24c02 8pin, 256 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
L200	2010	2015	25320	-	-	Philips® Crypto PH20 (46)
Lancer	1996	2003	24c01, 8pin, 128 Bytes	MT8SU/MT8SBTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Lancer	2008	2010	24c16 8pin, 2048 Bytes	MT8SU/MT8SBTK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Magna	1996	1999	93c46 8pin, 128 Bytes	-	-	Philips® fixed code PH00 (33)
Mirage	1996	2000	24c01, 8pin, 128 Bytes	MT8SU/MT8SBTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Montero	1996	2000	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
MITSUBISHI						
Montero	-	2007	24c02 8pin, 256 Bytes	-	-	Philips® Crypto PH20 (46)
Nativa	-	2008	24c02 8pin, 256 Bytes	-	-	Philips® Crypto PH20 (46)
Nimbus	1998	1999	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Outlander	-	2006	24c02 8pin, 256 Bytes	MT8SU/MT8SBTK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Pajero	1996	2000	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Pajero Sport	-	2007	24c02 8pin, 256 Bytes	-	-	Philips® Crypto PH20 (46)
Shogun	1996	2000	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Space Runner	1998	1999	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Space Star	1996	1999	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
NISSAN						
Interstar	1998	2001	Motorola MC68HC05B6 52pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Interstar	2002	2010	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Maxima	1995	1999	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Micra	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Primastar	2006	2013	95080, 8pin, 2048 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Primera	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Pulsar	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Serena	1996	1999	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Sunny	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Terrano II	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Vanette	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
OPEL/VAUXHALL						
Antara	2006	2010	95040, 8pin, 512 Bytes	OPL1U	TK100	Philips® Crypto PH20 (46)
Astra	-	2009	24c16 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Frontera	1996	1999	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Frontera	1999	2003	93c46 8pin, 128 Bytes	HD90U/HD90TK	TKM/GKM	Megamos® Crypto MG10 (48)
Insignia	-	2008	24c16 8pin, 2048 Bytes	VX5U/VX5BTK/VX5-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Movano	1998	2001	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Movano	1998	2001	93c56 8pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Movano	2002	2007	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Movano	-	2007	95080, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Vivaro	2002	2007	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Vivaro	-	2007	95080, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
PEUGEOT						
106	1997	2004	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
306	-	1997	Motorola MC68HC05E6, 28pin, 160 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
306	1997	1999	95040, 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
306	1997	1999	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
306	1997	2002	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
406	1997	1999	93c46 8pin, 128 Bytes	PG31U/PG31TK1	TK100	Philips® fixed code PH00 (33)
806	1998	2002	95040 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
806	1998	2002	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Bipper	-	2009	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Boxer	-	2001	93c46 8pin, 128 Bytes	FT50U/FT50TK	TK100/GKM	Megamos® fixed code MG00 (13)
Boxer	2006	2011	95320 8pin, 4096 Bytes	-	-	Megamos® Crypto MG10 (48)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
PEUGEOT						
Boxer	2006	2011	95160, 8pin, 2048 Bytes	-	-	Megamos® Crypto MG10 (48)
Expert	1998	2006	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Expert	1998	2006	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Expert	1998	2006	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Partner	1998	2001	93c46 8pin, 128 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Partner	-	2008	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Ranch	1998	2001	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Ranch	1998	2001	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Ranch	1998	2001	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
PEUGEOT MOTORBIKE						
Alise	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
Alise	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
Eliseo	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
Eliseo	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
Speedfight	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
Speedfight	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
PIAGGIO						
Beverly	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
Beverly	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
Liberty	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
Liberty	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
Vespa	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
Vespa	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
X8	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
X8	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
RENAULT						
Clio	1995	2001	93c46 8pin, 128 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Clio	1995	2001	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Clio	1995	2001	93c56 8pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Clio	1995	2001	93c56 8pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Clio	2001	2006	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Clio	2005	2012	95160, 8pin, 2048 Bytes	PG33U/PG33TK/PG33-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Espace	1997	2002	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Espace	2003	-	95160 8pin, 2048 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Kangoo	1998	2001	93c46 8pin, 128 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Kangoo	1998	2001	93c56 8pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Kangoo	2002	2009	93c66 8pin, 512 Bytes	VE20U/VE20TK/VE20-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Kangoo	-	2007	95080, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Laguna	1995	2001	93c46 8pin, 128 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Laguna	1995	2001	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Laguna	2000	2007	Motorola MC68HC912DG128 112pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Laguna	2000	2007	MC9S12DP256 112pin, 4096 Bytes	-	-	Philips® Crypto PH20 (46)
Master	1998	2001	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Master	1998	2001	93c56 8pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Master	2002	2007	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
RENAULT						
Master	-	2007	95080, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Mégane	1996	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Mégane	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Mégane	2003	2008	Motorola MC68HC912DG128 112pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Mégane	2003	2008	MC9S12DP256 112pin, 4096 Bytes	-	-	Philips® Crypto PH20 (46)
Modus	2004	2012	95160 8pin, 2048 Bytes	PG33U/PG33TK/PG33-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Safrane	1996	2000	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Scenic	2003	2008	Motorola MC68HC912DG128 112pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Scenic	2003	2008	MC9S12DP256 112pin, 4096 Bytes	-	-	Philips® Crypto PH20 (46)
Trafic	1997	2001	93c46 8pin, 128 Bytes	-	-	Philips® fixed code PH00 (33)
Trafic	1997	2001	93c56 8pin, 256 Bytes	-	-	Philips® fixed code PH00 (33)
Trafic	2002	2007	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Trafic	-	2007	95080, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Twingo	1996	2001	Motorola MC68HC05B16, 64pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Twingo	1996	2001	Motorola MC68HC05B6 52pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Twingo	2002	2007	93c66 8pin, 512 Bytes	VE20U/VE20TK/VE20-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
ROVER						
600	1998	2003	Motorola MC68HC05B6 52pin, 256 Bytes	RV3U/RV3TK1	TK100	Philips® fixed code PH00 (33)
618	1996	1999	Motorola MC68HC05B6 52pin, 256 Bytes	RV3U/RV3TK1	TK100	Philips® fixed code PH00 (33)
620	1996	1999	Motorola MC68HC05B6 52pin, 256 Bytes	RV3U/RV3TK1	TK100	Philips® fixed code PH00 (33)
800	1997	1998	Motorola MC68HC05B6 52pin, 256 Bytes	RV3U/RV3TK1	TK100	Philips® fixed code PH00 (33)
SEAT						
Alhambra	1996	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Alhambra	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Arosa	1997	1999	Motorola MC68HC05B16, 64pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Arosa	1997	1999	Motorola MC68HC05B6 52pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Cordoba	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Cordoba	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Ibiza	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Ibiza	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Inca	1996	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Inca	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Toledo	1995	1999	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Toledo	1995	1999	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
ŠKODA						
Felicia	1996	2001	Motorola MC68HC05B16, 64pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Felicia	1996	2001	Motorola MC68HC05B6 52pin, 256 Bytes	SK21STK1	-	Philips® fixed code PH00 (33)
Pick-up	-	1996	Motorola MC68HC05B16, 64pin, 256 Bytes	SK21SAP	-	Philips® fixed code PH00 (33)
Pick-up	-	1996	Motorola MC68HC05B6 52pin, 256 Bytes	SK21SAP	-	Philips® fixed code PH00 (33)
SUBARU						
Impreza	1996	2000	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Legacy	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Outback	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
SUZUKI						
Alto	1996	2002	24c01, 8pin, 128 Bytes	SU15U/SU15TK/SU15-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Baleno	1996	2001	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Carry	1999	2005	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Grand Vitara	1996	2002	24c01, 8pin, 128 Bytes	SU17U/SU17TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Jimny	1999	2002	24c01, 8pin, 128 Bytes	SU17U/SU17TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Super Carry	1999	2000	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Swift	1996	2005	93c66 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Swift	1996	2005	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Vitara	1996	2002	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Wagon R	1998	2000	24c01, 8pin, 128 Bytes	SU17U/SU17TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
TOYOTA						
Avensis	1998	2000	Motorola MC68HC05E6, 28pin, 160 Bytes	TR56U/TR56TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Camry	1996	2005	25080 8pin, 1024 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Camry	1996	2005	95080, 8pin, 2048 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2004	93c66 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	93c66 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	24c02 8pin, 256 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	25020 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	25080 8pin, 1024 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	95080, 8pin, 2048 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	93c56 8pin, 256 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Hiace	1995	2006	93c66 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Hiace	1995	2006	24c02 8pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Hiace	1995	2006	25020 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Hiace	1995	2006	25080 8pin, 1024 Bytes	-	-	Texas® fixed code TX00 (4C)
Hiace	1995	2006	95080, 8pin, 2048 Bytes	-	-	Texas® fixed code TX00 (4C)
Rav 4	1996	2004	93c66 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Rav 4	1996	2004	25080 8pin, 1024 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Rav 4	1996	2004	95080, 8pin, 2048 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Various	1996	2006	93c66 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Various	1996	2006	24c02 8pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Various	1996	2006	25020 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Yaris	1999	2005	24c02 8pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Yaris	1999	2005	25020 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Yaris	1999	2005	25080 8pin, 1024 Bytes	-	-	Texas® fixed code TX00 (4C)
Yaris	1999	2005	95080, 8pin, 2048 Bytes	-	-	Texas® fixed code TX00 (4C)
VOLKSWAGEN						
Caddy	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Caddy	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Cross fox	-	2003	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Fox	-	2003	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Gol	-	2008	93c56 8pin, 256 Bytes	V70U/V70TK	TKM/GKM	Megamos® Crypto MG10 (48)
Golf	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Golf	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Parati	-	2008	93c56 8pin, 256 Bytes	V70U/V70TK	TKM/GKM	Megamos® Crypto MG10 (48)
Passat	1994	1997	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
VOLKSWAGEN						
Passat	1994	1997	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Pointer	-	2004	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Polo	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Polo	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Santana	-	2007	93c56 8pin, 256 Bytes	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Saveiro	-	2008	93c56 8pin, 256 Bytes	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Sharan	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Sharan	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Space fox	-	2003	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
SportVan	-	2003	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Suran	-	2003	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Transporter	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Transporter	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Transporter	2003	2009	93c86(28000766), 8pin, 2048 Bytes	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Vento	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Vento	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
VOLVO						
850	1996	1997	93c46 8pin, 128 Bytes	VL17U/VL17TK1	TK100	Philips® fixed code PH00 (33)
940	1996	1998	93c46 8pin, 128 Bytes	VL10TK1	-	Philips® fixed code PH00 (33)
960	1996	1998	93c46 8pin, 128 Bytes	VL10TK1	-	Philips® fixed code PH00 (33)
C70	1997	1998	93c46 8pin, 128 Bytes	VL17U/VL17TK1	TK100	Philips® fixed code PH00 (33)
Polar	-	1996	93c46 8pin, 128 Bytes	VL10TK1	-	Philips® fixed code PH00 (33)
S40	1996	1998	93c46 8pin, 128 Bytes	VL15TK1	-	Philips® fixed code PH00 (33)
S70	1997	1998	93c46 8pin, 128 Bytes	VL17U/VL17TK1	TK100	Philips® fixed code PH00 (33)
V40	1996	1998	93c46 8pin, 128 Bytes	VL15TK1	-	Philips® fixed code PH00 (33)
V70	1997	1998	93c46 8pin, 128 Bytes	VL17U/VL17TK1	TK100	Philips® fixed code PH00 (33)